





# Replaces John Deere 1545 Rotary Mower Parts

62 & 72in Rear Discharge Deck - Model 2849  
60in Deck Parts



| Item No                            | R&R Part No. | OEM Part No.          | Description                             | Qty Req | Order Quantity |
|------------------------------------|--------------|-----------------------|-----------------------------------------|---------|----------------|
| <b>Rotary Blades</b>               |              |                       |                                         |         |                |
| 1                                  | RM144935     | M144935,<br>TCU51118  | Mower Blade - Mulcher - 22 x 3 x 1/4 in | 3       |                |
| <b>Belts</b>                       |              |                       |                                         |         |                |
| 20                                 | RTC14356     | TCU14356              | V-Belt - Fits 62 in Decks               | 1       |                |
| <i>Tech Note: Fits 62 in Deck:</i> |              |                       |                                         |         |                |
| <b>Other Parts Available</b>       |              |                       |                                         |         |                |
| 44                                 | RM141764     | M141764               | Eyebolt - Includes Flanged Locknut      | 1       |                |
| 45                                 | RM163054     | M163054               | Grass Deflector - Upper                 | 3       |                |
| 75                                 | RM127353     | M127353               | Bushing                                 | 3       |                |
| 76                                 | RM123569     | M123569               | Flange Nut                              | 3       |                |
| 76                                 | RM163055     | M163055               | Nut                                     | 3       |                |
| 77                                 | R253-133     | M85699                | Seal - Oil                              | 3       |                |
| 78                                 | RM88251      | M169375,<br>M88251    | Bearing - Spindle                       | 6       |                |
| 79                                 | RM127198     | M127198               | Seal                                    | 3       |                |
| 80                                 | R19M7489     | 19M7489               | Bolt Hex HD - M16 x 45 Gr 10.9          | 3       |                |
| 81                                 | RM115245     | M115245               | Roller                                  | 4       |                |
| 82                                 | RM123522     | M123522               | Washer - Belleville - Blade Bolt        | 3       |                |
| 83                                 | RTC14182     | TCU14182,<br>TCU38142 | Hub - Sub For TCU51119 or TCU14182      | 3       |                |
| 84                                 | RM123520     | M123520               | Washer - Hardened                       | 3       |                |
| 85                                 | R19M7868     | 19M7868               | Bolt - M8-1.25 x 30 HHF                 | 30      |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces John Deere 1545 Rotary Mower Parts

62 & 72in Rear Discharge Deck - Model 2849  
60in Deck Parts



| Item No | R&R Part No.     | OEM Part No.        | Description                                     | Qty Req | Order Quantity |
|---------|------------------|---------------------|-------------------------------------------------|---------|----------------|
| 87      | <b>RTCA17524</b> | TCA17524            | Idler Pulley - 5 in Flat Dia with .75 in Brg ID | 2       |                |
| 90      | <b>RM163059</b>  | M163059             | Spindle - 25 mm w/M16-2.0 Blade Bolt Thrd       | 3       |                |
| 90      | <b>RM134382</b>  | M134382             | Spindle - 25 mm w/M12-1.75 Blade Bolt Thrd      | 3       |                |
| 91      | <b>RM141695</b>  | M112398,<br>M141695 | Idler - North America (Replaces M112398)        | 1       |                |
| 92      | <b>R24M7226</b>  | 24M7226             | Washer - 13 x 35 x 5 mm                         | 1       |                |
| 93      | <b>RTC51223</b>  | TCU51223            | Deflector - Grass                               | 3       |                |
| 94      | <b>RM124203</b>  | M124203             | Shaft                                           | 1       |                |
| 95      | <b>RM136044</b>  | M136044             | Spring - Extension                              | 1       |                |
| 96      | <b>RM133598</b>  | M133598             | Shield                                          | 2       |                |
| 97      | <b>R14M7400</b>  | 14M7400             | Locknut - 10mm                                  | 3       |                |
| 101     | <b>RM163058</b>  | M127517,<br>M163058 | Bushing - Sub For M127517                       | 3       |                |
| 103     | <b>R93-2559</b>  | TCU23201            | Bearing                                         | 2       |                |
| 104     | <b>RM132309</b>  | M132309             | Spacer                                          | 2       |                |
| 105     | <b>RM163060</b>  | M133398,<br>M163060 | Washer - Replaces RM133398                      | 3       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.