




## Replaces Scag STTII - Turf Tiger II Parts

72in Zero-Turn Mower

72in Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Scag STTII - Turf Tiger II Parts

72in Zero-Turn Mower  
72in Deck



| Item No                      | R&R Part No.        | OEM Part No.      | Description                                        | Qty Req | Order Quantity |
|------------------------------|---------------------|-------------------|----------------------------------------------------|---------|----------------|
| 1                            | <b>RRB3170-2400</b> | 482882            | Mower Blade - High-Lift 24.5 x 2.5in x 5/8 Mt Hole | 3       |                |
| <b>Wheels</b>                |                     |                   |                                                    |         |                |
| 10                           | <b>RZS481632</b>    | 481632            | Wheel - Anti Scalp                                 | 2       |                |
| 11                           | <b>RZS482295</b>    | 482295            | Wheel - Anti Scalp                                 | 3       |                |
| <b>Belts</b>                 |                     |                   |                                                    |         |                |
| 20                           | <b>RZS481558</b>    | 481558,<br>481980 | Belt - 61V Deck Drive                              | 1       |                |
| <b>Other Parts Available</b> |                     |                   |                                                    |         |                |
| 40                           | <b>RZS461663</b>    | 461663            | Spindle Assembly                                   | 3       |                |
| 41                           | <b>RZS43644</b>     | 43644             | Spindle Housing                                    | 3       |                |
| 42                           | <b>RZS43589</b>     | 43589             | Spindle Shaft                                      | 3       |                |
| 43                           | <b>R366649</b>      | 481024            | Seal                                               | 3       |                |
| 44                           | <b>RZS481022</b>    | 481022            | Bearing Assembly                                   | 3       |                |
| 45                           | <b>RZS43312</b>     | 43312             | Spacer - Outside                                   | 3       |                |
| 47                           | <b>RZS43296</b>     | 43296             | Spacer - Inside                                    | 3       |                |
| 49                           | <b>RZS481025</b>    | 481025            | Seal - Bottom                                      | 3       |                |
| 50                           | <b>RZS43297</b>     | 43296,<br>43297   | Spindle Bushing                                    | 3       |                |
| 51                           | <b>RZS481035</b>    | 481035            | Nut - Special 1-1/16 - 18                          | 3       |                |
| 52                           | <b>RZS43590</b>     | 43590             | Spacer - Spindle Bottom                            | 3       |                |
| 54                           | <b>RZS461842</b>    | 461842            | Idler Arm Weldment - with Bearing                  | 1       |                |
| 55                           | <b>RZS48224</b>     | 48224             | Bearing                                            | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Scag STTII - Turf Tiger II Parts

72in Zero-Turn Mower

72in Deck



| Item No | R&R Part No.     | OEM Part No. | Description               | Qty Req | Order Quantity |
|---------|------------------|--------------|---------------------------|---------|----------------|
| 57      | <b>RZS43681</b>  | 43681        | Pivot - Idler             | 1       |                |
| 59      | <b>RZS461516</b> | 461516       | Push Arm Assembly LH & RH | 2       |                |
| 60      | <b>RZS48038</b>  | 48038        | Guide Roller              | 1       |                |
| 61      | <b>RZS451240</b> | 451240       | Rod Weldment - Pusharm    | 1       |                |
| 64      | <b>RZS422478</b> | 422478       | Bracket - Anti Scalp      | 2       |                |
| 66      | <b>RZS483215</b> | 483215       | Pulley - Idler 5 in       | 1       |                |
| 68      | <b>R170714</b>   | 48677        | Fitting - Pressure Relief | 3       |                |
| 69      | <b>R302-5</b>    | 48114-04     | Fitting - Grease          | 3       |                |
| 70      | <b>RZS483704</b> | 483704       | Spring                    | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.