



3 Viton TU2K Ind Ball Check Valvee Repair Kit RGCK2VRK030



Details

Repair kits for True Union 2000 Single Entryl Ball Check Valves.

Specifications

Manufacturer	Spars
Fitting Size	3
Seal Type	Viton

Golfmech Ltd

Hullaghfin Balrath Navan, C15 VOFS
353 87 632 9827

<https://golfmech.rrproducts.com/>