



NGK Spark Plug - R7435-10

RN4897



Replaces

Autolite	4051
----------	------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Golfmech Ltd

Hullaghfin Balrath Navan, C15 VOFS
353 87 632 9827

<https://golfmech.rrproducts.com/>